

COMMONWEALTH AIRCRAFT, INC.

<u>Model & T.C. No.</u>	<u>S.T.C. No.</u>	<u>Description</u>	<u>Name & Address of Holder</u>
175; T.C. A-729	SA798EA Reissued 14Feb72	Installation of Monitair exhaust gas combustion monitor kit.	Rosemount Engineering Company 12001 West 78th Street Eden Prairie, Minnesota 55343
175, 180, 180F, 185, 190F; T.C. 729	SA4-302	EN-1 propeller spinner.	Raymond M. Stits 3665 Bloomington Blvd. Riverside, Calif.
	SA4-1208	Ceconite covering of complete aircraft.	Cooper Engr. Co. P.O. Box 3428 Van Nuys, Calif.
175, 180, -F, 183, 190F, T. C. 729 6000M; T. C. 661 9000; T. C. 624	SA1351WE (Reissued 6Mar69)	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces with Ceconite 101 material.	Ceconite, Inc. 4677 Worth Street Los Angeles, California
175, 180, F, 185, 190F; T. C. A-729	SA308EA Amended 11Jun71	Installation of carburetor ice detection system 105AP in single and twin engine FAR 23/CAR 3 aircraft equipped with Marvel-Schubler series carburetor.	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L. I., New York 11743
	SA489EA Amended 11Jun71	Installation of carburetor ice detection system.	Alfred R. Puccinelli DER 1-145 36 Bay Drive East Huntington, L.I., New York 11743
185; T.C. 729	SA2-952	Fiberglass covering of airplane.	Razorback Fabrics, Inc. Manila, Arkansas 72442
	SA4-901	Fiberglass covering on wings.	Clasco-Air Products Oxnard-Ventura County Airport, Oxnard, Calif.
	SA1008WE (Amended 8/7/69)	Installation of Poly-Fiber covering material.	Stits Aircraft Corporation P.O. Box 3084 Riverside, California 92509
6000M; T.C. 661	SA441WE	Ceconite 101 covering of fuselage.	Cooper Engr. Co. P.O. Box 3428 Van Nuys, Calif.
7000, 9000L; T.C. 574, 591	SA519WE	Wheel adapters on Goodyear wheels 3LMBM.	Robert P. Lamb 2998 Daisy Ave. Long Beach, Calif.
9000, 9000 Deluxe; T.C. 624	SA229WE	Ceconite 101 covering of wings, ailerons, horizontal stabiliser, elevators, vertical fin and rudder.	Cooper Engr. Co. P.O. Box 3428 Van Nuys, Calif.

Rev. 6/30/72